


## Vapor pressure curves for vacuum brazing



Under reduced pressure, the boiling point of metals is lowered. For combinations of temperatures and pressures lying left of the curve, the metal is a liquid or solid. To the right of the curve it is a vapor.

Information is subject to change without prior notice.